


Lay this edge along the lathe tool-rest adjacent to the stock



DIAMETERS {

- 16 mm
- 20 mm
- 25 mm

**Marking Stick for
Drascombe Lugger
Belaying Pin** 

Print this out at full size, paste it on card or thin ply and use it for setting out the blank stock in the lathe